

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:	
Company	Dennis Oakley Environmental Engineer	
OGM	OGM Steve Demczak Environmental Scientist I	

Inspection Report

Permit Number:	C0150017		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, March 23, 2009		
Start Date/Time:	3/23/2009 10:00:00 AM		
End Date/Time:	3/23/2009 1:00:00 PM		
Last Inspection:	Tuesday, February 10, 2009		

Inspector: Steve Demczak, Environmental Scientist III

Weather: <u>Sunny, Windy, 40's</u> InspectionID Report Number: <u>1958</u>

Accepted by: jhelfric 4/6/2009

Oil, Gas & Mining

JOHN R. BAZA

Division Director

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: **DES BEE DOVE MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Mineral Ownership

Types of Operations

134.31	Total Permitted		
36.02	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Current Acreages

Federal

State

☐ County

Fee Other

✓ Underground☐ Surface☐ Loadout

Processing
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were written or pending.

Inspector's Signature:

Steph Demyk Steve Demozak, Environmental Scientist III

Date

Monday, March 30, 2009

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, March 23, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	V		✓	
13.	Revegetation	V		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	a Roads: Construction, Maintenance, Surfacing		V		
16.Ł	Roads: Drainage Controls		~		
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, March 23, 2009

Page 3 of 3

3. Topsoil

All topsoil was used during reclamation.

4.a Hydrologic Balance: Diversions

No water was flowing within the diversions.

4.c Hydrologic Balance: Other Sediment Control Measures

The reclamation site was completely pocked for sediment control.

8. Noncoal Waste

No non-coal waste could be seen.

10. Slides and Other Damage

No slides or other damage were noticed during the inspection.

12. Backfilling And Grading

The site is completely backfilled and graded.

13. Revegetation

The site was seeded.

21. Bonding and Insurance

The insurance will expire on Aug. 28, 2009.